

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-045-29225	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name: Woods Gas Com B	
Well No. 1	
9. Pool name or Wildcat Kutz Pictured Cliffs, West	

SUNDRY NOTICES AND REPORTS ON WELLS.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
BP America Production Company Attn: **Cherry Hlava**

3. Address of Operator
P.O. Box 3092 Houston, TX 77253

4. Well Location
Unit Letter **M** **1520** feet from the **South** line and **1150** feet from the **West** line
Section **7** Township **29N** Range **12W** NMPM **San Juan** County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
5476'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER:	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: Drilled out CIBP - Change from TA status <input checked="" type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Approval to T&A was granted 7/15/02. Well was T&A'd on 7/7/03 and subsequent report was approved 1/17/03.

Inadvertently the CIBP was drilled out. Please see report below:

4/18/06 Tested Lines to 2000 psi; good test.
4/20/06 TIH drilled out CIBP @1446'. TIH & set 3.5" RBP @1409' for wellhead change. Test CSG & RBP to 250 psi. Held 5 min. Good test. Install wellhead; install new casing valves. Pressure test function pmp to 1000 psi. Held 10 min. Good tests. Latch onto RBP & remove.
4/24/06 TIH & land tbg @1563'.

The well is currently shut in waiting for a compressor.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cherry Hlava TITLE Regulatory Analyst DATE 08/03/2006
Type or print name Cherry Hlava Telephone No. 281-366-4081

(This space for State use)
APPROVED BY H. Villanueva TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 8 DATE AUG 08 2006
Conditions of approval, if any: