




NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

Date of Test 7-27-06 Operator Dugan Production Corp. API # 30-045-30246
Property Name Mayre Well No. 90R Location: Unit N Section 31 Township 30N Range 14W
Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate Casing 17 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		17			
10 minutes	0		17			
15 minutes	0		17			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE


Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

By  Witness
Switcher
(Position)