



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

Due 11-5-06

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 8-2-06 Operator Burlington Resources API #30-0 45-09643
Property Name McCord Well No. 11 Location: Unit N Section 9 Township 30 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 325 Intermediate N/A Casing 325 Bradenhead 143

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min			320		
10 min			320		
15 min			320		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow ☒	
Surges	
Down to Nothing	
Nothing	
Gas ☒	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 11

INTERMEDIATE N/A

REMARKS:

did not blow down in 15 minutes

By Chris Hoff
MSO
(Position)

Witness Monica Cuchling

E-mail address _____

Failure