



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 08/11/06 Operator Masa/EX API #30-0 45-31909

Property Name Blanca Well No. 1 Location: Unit 6 Section 24 Township 30 Range 12

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 90 Bradenhead 98

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	<u>TSTM</u>		<u>90</u>		
10 min	<u>TSTM</u>		<u>90</u>		
15 min	<u>TSTM</u>		<u>90</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE _____ BRADENHEAD TSTM INTERMEDIATE _____

REMARKS:

Bradenhead Bleed down TSTM in 30 seconds

By Steven R. Szumanski
Pumper
(Position)

Witness Matthew Peltz

E-mail address _____

