



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/28/2006 Operator Elk San Juan, Inc. API #30-045-33562

Property Name Ute Mtn Triba Well No. 35-D Location: Unit I Section 35 Township 31S Range 15W

Well Status (Shut-In or Producing) Initial PSI: Tubing 90# Intermediate N/A Casing 465# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0#</u>	<u>X</u>	<u>465#</u>		
10 min	<u>0#</u>	<u>X</u>	<u>465#</u>		
15 min	<u>0#</u>	<u>X</u>	<u>465#</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>IN 10 sec</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0#

INTERMEDIATE N/A

REMARKS:

LONG STRING production NO intermediate CSG.

By

Greg Vick

Witness

Jerry Jaramilla

Consultant for Elk San Juan
(Position)

E-mail address gregvick@mvc.i.biz