## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test	8/22/66 Operator	Dugan Production Corp. API #		30-045-05765	
	,	Well No. 1 Location:			
Well Status(Shu	ut-In or Producing) Initial PSI:	Tubing <u>155</u> Intermedia	ate NA	Casing	Bradenhead 🗢
TIME 5 mintues 10 minutes 15 minutes	PRESSURE Bradenhead Interm BH Int Csg Int Csg	Steady Flow Surges Down to Nothing	FLOW BRADI	LY FOR 15 MINUTES  CHARACTERISTICS  ENHEAD INTERM	
20 minutes		Nothing	-		
25 minutes		Gas			<del></del> :
30 minutes		Gas & Water			
<u>If bradenh</u>		ck all of the description FRESHSALTY			<del></del>
5 MINUTE S	SHUT-IN BRADENHE	AD	INTERMEDIAT	E	
	Ker in We	(			
					<del></del>
					- STATE OF THE STA
Ву	Alonzo Harr	<del>(y</del>	Witness		
	Switcher (Position)	<del></del>		f. s	2 SEP 2006
	(i contoll)				