

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3ddistrict.htm](http://emnrd.state.nm.us/ocd/District%20III/3ddistrict.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 8/22/06 Operator Dugan Production Corp. API # 30-045-05914
Property Name Hanson Federal Well No. 1 Location: Unit M Section 11 Township 26N Range 11W
Well Status(Shut-In or Producing) Initial PSI: Tubing 275 Intermediate NA Casing Ø Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead			Interm			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes	Ø		Ø					Steady Flow
10 minutes	Ø		Ø					Surges
15 minutes	Ø		Ø					Down to Nothing
20 minutes						Ø		Nothing
25 minutes								Gas
30 minutes								Gas & Water
								Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN


BRADENHEAD

Ø

INTERMEDIATE

REMARKS:

Tacker in well



By

Alonzo Harvey

Witness

Switcher

(Position)