NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	ate of Test 8/17/06 Operator			Productio	API#	± 30-045-22938							
Property Name	Blanco	Wash	Well No.	4	Location: Unit	A	Section	2	Township	24N	- Range	9W	
Well Status(Shut-In or Producing) Initial PSI:		Tubing _	20	Intermediate		Casing	3	35	Bradent	nead .	0		
	5 mintues 10 minutes 15 minutes 20 minutes 25 minutes 35			Steady Flow Surges Down to Nothing Nothing Gas Gas & Water Water		IVIDUAL FLOW		15 N	MINUTES				
If bradenhead flowed water, check all of the descriptions that apply below:													
5 MINUTE S	CLEAR	BRADENHE	_FRESH _	D	_SALTYINTE	SULFU		BLAC	Kim Ste	SEP 2	2006 - 100 -	17 10 10 70 J	
Ву	ANI	Switcher (Position)			Witn	ess					- - -		