

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrnd.state.nm.us/ocd/District III/3district.htm](http://emnrnd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**  
(Submit 1 copy to above address)

Date of Test 8/26/06 Operator Dugan Production Corp. API # 30-045-24644  
Property Name Aloha Well No. 1 Location: Unit L Section 16 Township 28N Range 11W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate X Casing 10 Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE						FLOW CHARACTERISTICS	
	Bradenhead		Interm				BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg			
5 minutes	N/A	X	10					Steady Flow
10 minutes								Surges
15 minutes								Down to Nothing
20 minutes								Nothing
25 minutes								Gas
30 minutes								Gas & Water
								Water

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD N/A INTERMEDIATE \_\_\_\_\_

REMARKS:

No Braden head found

By \_\_\_\_\_

Chris Pike

Witness \_\_\_\_\_

Switcher

(Position)

