

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 8/17/06 Operator Dugan Production Corp. API # 30-045-25919
Property Name Muddy Mudda Well No. 1 Location: Unit D Section 21 Township 24N Range 9W
Well Status(Shut-In or Producing) Initial PSI: Tubing 5 Intermediate Casing 18 Bradenhead X

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>18</u>		<u>18</u>			
10 minutes	<u>18</u>		<u>18</u>			
15 minutes	<u>18</u>		<u>18</u>			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK


5 MINUTE SHUT-IN

BRADENHEAD

INTERMEDIATE

REMARKS:

By


Switcher
(Position)

Witness

