

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 7/27/06 Operator Dugan Production Corp. API # 30-045-30314
Property Name Leah Marie Well No. 3 Location: Unit E Section 23 Township 26N Range 12W
Well Status(Shut-In or Producing) Initial PSI: Tubing 5 Intermediate NA Casing 15 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead	Int	Csg	Int	Csg	BRADENHEAD	INTERMEDIATE
5 minutes	0		15			Steady Flow	
10 minutes	0		15			Surges	
15 minutes	0		15			Down to Nothing	
20 minutes	0		15			Nothing	X
25 minutes	0		15			Gas	
30 minutes	0		15			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR ☒ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN

BRADENHEAD

INTERMEDIATE

REMARKS:



By

Calvin A. Zohary

Switcher

(Position)

Witness