

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emrds.state.nm.us/ocd/District III/3district.htm](http://emrds.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 8-22-06 Operator Dugan Production Corp. API # 30-045-30732  
Property Name Riviera Com Well No. 2 Location: Unit E Section 18 Township 30N Range 14W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 80 Intermediate            Casing 48 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	<u>0</u>		<u>48</u>			
10 minutes	<u>0</u>		<u>48</u>			
15 minutes	<u>0</u>		<u>48</u>			
20 minutes						
25 minutes						
30 minutes						

Steady Flow  
Surges  
Down to Nothing  
Nothing  
Gas  
Gas & Water  
Water

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

BRADENHEAD	INTERMEDIATE
<u>0</u>	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR            FRESH            SALTY            SULFUR            BLACK           

**5 MINUTE SHUT-IN**

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By

[Signature]

Switcher  
(Position)

Witness

