

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 8/17/06 Operator Dugan Production Corp. API # 30-045-33187  
Property Name Bitsili Com Well No. 90 Location: Unit G Section 19 Township 24N Range 9W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 10 Intermediate \_\_\_\_\_ Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

	Bradenhead			Interm		
TIME	BH	Int	Csg	Int	Csg	
5 minutes	0		40			
10 minutes						
15 minutes	0		40			
20 minutes						
25 minutes	0		40			
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
X	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

INTERMEDIATE

REMARKS:

By

*Luke Dool*  
Switcher  
(Position)

Witness

