



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7/25/06 Operator KUKUI API # 30-045-27618
713-658-1988

Property Name ANGEL PEAK BM #1 Location: Unit M Section 13 Township 27N Range 10W
(Well Name and Number)

Pressure (Shut-in or Producing) Producing Tubing 2 Intermediate — Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>0</u>	<u>20</u>	<u>—</u>			Steady Flow	
10 minutes	<u>0</u>	<u>20</u>	<u>—</u>			Surges	
15 minutes	<u>0</u>	<u>20</u>	<u>—</u>			Down to Nothing	
20 minutes	<u>0</u>	<u>20</u>	<u>—</u>			No Flow	<u>✓</u>
25 minutes	<u>0</u>	<u>20</u>	<u>—</u>			Gas	
30 minutes	<u>0</u>	<u>20</u>	<u>—</u>			Gas and Water	
5 minute SI	<u>0</u>	<u>20</u>	<u>—</u>			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur —

Black —

5 Minute Shut-in Bradenhead 0 Intermediate —

REMARKS:

by LUCKY WASATEA
PUMPER
(Position)

Witness —