



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178, FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8/30/06 Operator KUKUI-WALSH API # 30-045-27741
713-658-1888
Property Name ANGEL PEAK 11A#4 Location: Unit A Section 11 Township T27N Range R10W
(Well Name and Number)
Pressure (Shut-in or Producing) Tubing 2 Intermediate — Casing 12 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>12</u>				Steady Flow	
10 minutes	<u>0</u>	<u>12</u>				Surges	
15 minutes	<u>0</u>	<u>12</u>				Down to Nothing	
20 minutes	<u>0</u>	<u>12</u>				No Flow	
25 minutes	<u>0</u>	<u>12</u>				Gas	
30 minutes	<u>0</u>	<u>12</u>				Gas and Water	
5 minute SI	<u>0</u>	<u>12</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead 0 Intermediate —

REMARKS:

by LUCKY LASATER
PUMPER
(Position)

Witness —