



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9/13/06 Operator KUKUE-WALSH API # 30-045-27826
Property Name ANGEL PEAK 92#10 Location: Unit L Section 169 Township 127N Range 10W
(Well Name and Number)
Pressure (Shut-in or Producing) Producing Tubing 5 Intermediate --- Casing 8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>8</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
10 minutes	<u>0</u>	<u>8</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
15 minutes	<u>0</u>	<u>8</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
20 minutes	<u>0</u>	<u>8</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
25 minutes	<u>0</u>	<u>8</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
30 minutes	<u>0</u>	<u>8</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>
5 minute SI	<u>0</u>	<u>8</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>	<u>---</u>

Steady Flow ---
Surges ---
Down to Nothing ---
No Flow ✓
Gas ---
Gas and Water ---
Water ---

If bradenhead flowed water, check all of the descriptions that apply below:

Clear --- Fresh --- Salty --- Sulfur --- Black ---

5 Minute Shut-in Bradenhead 0 Intermediate ---

REMARKS:

by LUCKY WASATEA
PUMPER
(Position)

Witness ---