



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 8/30/06 Operator KUKUI-WALSH API # 30-045-27839
713-658-1888

Property Name ANGEL PEAK 242#9 Location: Unit L Section 24 Township T21N Range R10W
(Well Name and Number)

Pressure (Shut-in or Producing) 0 Tubing 3 Intermediate — Casing 9 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>9</u>	<u>1</u>				
10 minutes	<u>0</u>	<u>9</u>	<u>1</u>				
15 minutes	<u>0</u>	<u>9</u>	<u>1</u>				
20 minutes	<u>0</u>	<u>9</u>	<u>1</u>				
25 minutes	<u>0</u>	<u>9</u>	<u>1</u>				
30 minutes	<u>0</u>	<u>9</u>	<u>1</u>				
5 minute SI	<u>0</u>	<u>9</u>	<u>1</u>				

Steady Flow		
Surges		
Down to Nothing		
No Flow	<u>✓</u>	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear — Fresh — Salty — Sulfur — Black —

5 Minute Shut-in Bradenhead 0 Intermediate —

REMARKS:

by LARRY LASATTA
PUMPBA
(Position)

Witness —