



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 9-27-06 Operator Mountain States API # 30-0 31-07025

Property Name Hospah Sand Unit Well # 61 Location: Unit F Sec 1 Twn 17 Rge 9

Land Type:

State _____
Federal _____
Private ☒ _____
Indian _____

Well Type:

Water Injection ☒ _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N) _____ TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. N/A Tbg. Inj. Pres. _____
Tubing Pres. N/A
Int. Casing Pres. N/A

Pressured annulus up to 605 psi. for 30 mins. Test passed/failed

REMARKS:

No Bradenhead -
dropped to 580 & held


By Cory B. B.
(Operator Representative)

Witness Monica Cukling
(NMOCD)

(Position)

Revised 02-11-02

B2



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1000-150F
927-06
1-17-9

METER _____

CHART PUT ON _____

TAKEN OFF _____

LOCATION: *Hospital Sand Lot #6*

REMARKS: *30-031-07025*

Monica K. Kelling