

1000 Rio Brazos Road
Aztec, New Mexico

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	8/1/2006	Operator	Burlington Resources Oil & Gas
--------------	----------	----------	--------------------------------

Lease Name MCCORD Well No 6E Location: U P Sec. 09 Twp. 030N Rge. 013W

Pressure (Flowing) Dwt	Tubing	294	Intermediate	Casing	1057	Bradenhead	37
------------	---------	-------	--------	-----	--------------	--------	------	------------	----

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

TIME:	PRESSURES:		BRADENHEAD FLOWED:	INTERMEDIATE FLOWED:
	INTERMEDIATE	CASING		
5 Min.		1057	Steady Flow	
10 Min.		1057	Surges	
15 Min.		1057	Down to Nothing	X
20 Min.			Nothing	
25 Min.			Gas	X
30 Min.			Gas & Water	
			Water	

If Bradenhead flowed water, check description below:

Clear _____

Fresh _____

Salty _____

Sulfur _____

Black _____

Remarks: _____

Ending: BH Press.: 0 Interm. Press. Down

BH had 37psi. Blew down in 23sec. 15min
~~test, and~~ no build up after 5min shut
in.

By CONTRACTOR - CHRIS HUFF 387
Lease Operator

Position

Witness

DPNO: 3251902

