



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

9/27/06

Operator

LUCKY HASATER

API #

3004527748

Property Name

ANGEL PEAK 15M#7

Location: Unit

Section

15

Township

T27N

Range

R10W

(Well Name and Number)

Pressure (Shut-in or Producing)

Tubing

5

Intermediate

—

Casing

12

Bradenhead

0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	12					
10 minutes	0	12					
15 minutes	0	12					
20 minutes	0	12					
25 minutes	0	12					
30 minutes	0	12					
5 minute SI	0	12					
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear

—

Fresh

—

Salty

—

Sulfur

—

Black

SEP 2006

5 Minute Shut-in

Bradenhead

0

Intermediate

—

REMARKS:

by

LUCKY HASATER

Witness

PUMPER

(Position)