

RCVD OCT25 01  
OIL CONS. DIV.  
DIST. 3

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emrmd.state.nm.us/ocd/District\\_III/3district.htm](http://emrmd.state.nm.us/ocd/District_III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 8-17-06 Operator Dugan Production Corp. API # 30-045-22583  
 Property Name Bengal C Well No 3 Location: Unit A Section 36 Township 27N Range 13W  
 Well Status(Shut-In or Producing) Initial PSI: Tubing 70.0 Intermediate N/A Casing 131.4 Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		131		
10 minutes	0		131		
15 minutes	0		131		
20 minutes					
25 minutes					
30 minutes					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR  FRESH  SALTY  SULFUR  BLACK

5 MINUTE SHUT-IN BRADENHEAD N/A INTERMEDIATE N/A

REMARKS:

NO Braden head

---



---



---

By *Oron M. Gage*  
 \_\_\_\_\_  
 Switcher  
 (Position)

Witness \_\_\_\_\_