

RCVD OCT25'06

OIL CON. DIV.

DIST. 3

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test Oct 3, 06 Operator Dugan Production Corp. API # 30-045-24636  
 Property Name MF Well No. 1 Location: Unit L Section 18 Township 24N Range 9W  
 Well Status(Shut-In or Producing) Initial PSI: Tubing 60 Intermediate N/A Casing 63 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

## PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	6		63			
10 minutes	0		63			
15 minutes	0		63			
20 minutes	0		63			
25 minutes	0		63			
30 minutes	0		63			

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas &amp; Water

Water

## FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
✓	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By

Alonso Hervey

Switcher

(Position)

Witness