NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Data of Task	Dugan Production Corp.			ADI #	20.045	25497				
										0)4/
Property Name April Surprise		_vveii No	4	_Location: Un	It <u>L</u>	_Section .	Townsr	nip <u>24N</u> Ra	nge <u>9۷۷</u>	
Well Status(Shut-In or Producing) Initial PSI:			Tubing_	35	_Intermediate_	_N/A	_Casing _	35	Bradenh <u>ead</u>	1-6
10 minutes			FO ATMO Steady Flow Surges Down to No Nothing	, , thing	FLOW		reristics	ES EACH		
25 minutes	-]	Gas						
30 minutes			1	Gas & Wate	 er					
Water										
If bradenhead flowed water, check all of the descriptions that apply below: CLEARFRESHSALTYSULFURBLACK										
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE										
Ву		<i>y Harre</i> Switcher	mz_		w	itness				
		(Position)								