

RCVD OCT25'06
OIL CONS. DIV.
DIST. 3

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 9-7-06 Operator Dugan Production Corp. API # 30-045-25711
Property Name Hugh Lake Well No. 2 Location: Unit A Section 29 Township 27N Range 12W
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 0 Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE						FLOW CHARACTERISTICS	
TIME	Bradenhead			Interm		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
5 mintues							
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

N/A

INTERMEDIATE

N/A

REMARKS:

NO BRADENHEAD

By

[Signature]

Witness

Switcher

(Position)