

RCVD OCT25'06
OIL CONS. DIV.
DIST. 3

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 9-7-06 Operator Dugan Production Corp. API # 30-045-25729
Property Name Coaly Well No. 1 Location: Unit K Section 28 Township 27N Range 12W
Well Status(Shut-In or Producing) Producing Initial PSI: Tubing 0 Intermediate N/A Casing 0 Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead	Int	Csg	Int	Csg	BRADENHEAD	INTERMEDIATE
5 minutes							
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD N/A INTERMEDIATE N/A

REMARKS:

no meter for gas well produces water only

By

Doc m

Witness _____

Switcher

(Position)