

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 8-17-06 Operator Dugan Production Corp. API # 30-045-26092  
Property Name Irish Well No. 3 Location: Unit L Section 11 Township 26N Range 13W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 12 Intermediate N/A Casing 22 Bradenhead N/A

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes					
10 minutes					
15 minutes					
20 minutes					
25 minutes					
30 minutes					

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN

BRADENHEAD

N/A

INTERMEDIATE

N/A

REMARKS:

NO Braden head

By [Signature] Witness \_\_\_\_\_  
Switcher  
(Position)