

RCVD OCT25'06  
OIL CONS. DIV.  
DIST. 3

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 10-5-06 Operator Dugan Production Corp. API # 30-045-26997  
Property Name March On Well No. 1 Location: Unit F Section 32 Township 24 Range 9W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 34 Intermediate        Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		40		
10 minutes	0		40		
15 minutes	0		40		
20 minutes	0		40		
25 minutes	0		40		
30 minutes	0		40		

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

BRADENHEAD	INTERMEDIATE
X	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

0

INTERMEDIATE \_\_\_\_\_

REMARKS:

By

Randy Anderson

Switcher

(Position)

Witness \_\_\_\_\_