

RCVD OCT25'06  
OIL CONS. DIV.  
DIST. 3

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 8-17-06 Operator Dugan Production Corp. API # 30-045-29433  
Property Name Dome Navajo 12-26-13 Well No. 90 Location: Unit K Section 12 Township 26N Range 13W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 5.8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 mintues	0		5.8			
10 minutes	0		5.8			
15 minutes	0		5.8			
20 minutes						
25 minutes						
30 minutes						

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD	INTERMEDIATE
X	

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

0

INTERMEDIATE

N/A

REMARKS:

By

Joe M. [Signature]

Witness

Switcher

(Position)