

RCVD OCT25'06
OIL CONS. DIV.

DIST. 3

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 9-7-06 Operator Dugan Production Corp. API # 30-045-29829
Property Name Hugh Lake Well No. 90 Location: Unit M Section 33 Township 27N Range 12W
Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		0			
10 minutes	0		0			
15 minutes	0		0			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

N/A

REMARKS:

well not pumping

By

Joan M. [Signature]

Witness

Switcher

(Position)