

RCVD OCT25'06

OIL CONS. DIV.

DIST. 3

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENTOil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 8-17-06 Operator Dugan Production Corp. API # 30-045-29832
 Property Name Kingfish Com Well No. 90 Location: Unit H Section 3 Township 26N Range 13W
 Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 37 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm	
	BH	Int	Csg	Int	Csg
5 minutes	0		37		
10 minutes	0		37		
15 minutes	0		37		
20 minutes					
25 minutes					
30 minutes					

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD INTERMEDIATE

BRADENHEAD	INTERMEDIATE
X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD


0

INTERMEDIATE

N/A

REMARKS:

By



Switcher

(Position)

Witness