

RCVD OCT25'06

OIL CONS. DIV.

DIST. 3

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 8-17-06 Operator Dugan Production Corp. API # 30-045-29833
 Property Name Irish Well No. 4 Location: Unit I Section 12 Township 26N Range 13W
 Well Status(Shut-In or Producing) Initial PSI: Tubing 8 Intermediate N/A Casing 9 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		9			
10 minutes	0		9			
15 minutes	0		9			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

BRADENHEAD

INTERMEDIATE

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

N/A

REMARKS:

By

Joe MSA

Witness

Switcher

(Position)