

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 8-22-06 Operator			Dugan Production Corp.				API#	30-045-29875				
	Paul F										26N Rang	ge 13
Well Status(Sh			_		4			.5	Bradenh <u>ead</u>	0		
OPEN BRAI	DENHEAD AN PRES Bradenhead		EDIATE 1	ГО АТМС	SPHERE	E IND					EACH	
TIME	BH Int Csg					FLOW CHARACTERISTICS BRADENHEAD INTERME				DIATE		
5 mintues	0 3	Int Csg]	Steady Flov	N							
10 minutes	0 5,5		1	Surges	•							
15 minutes) 5.3	1	7	Down to No	athing							
20 minutes			1	Nothing	ing .		\(\)					
25 minutes				Gas								
			1								-	
30 minutes			Gas & Water									
				Water							•	
<u>If bradenh</u>	ead flowed	water, che	ck all o	f the de	scriptio	ns th	at apply	y belov	<u>v:</u>			
	CLEA	R	_FRESH_		_SALTY		SULFU	R	BLAC	K	_	
5 MINUTE SHUT-IN BRADENHEARREMARKS:			AD .	0	_	INTE	RMEDIATE	<u> </u>	h	_		
							,					
Ву	Doc	- M SN 2				Witne	ess					
·		Switcher	-							·		

(Position)