

RCVD OCT26'06

OIL CONS. DIV.

DIST. 3

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENTOil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 10-24-06 Operator Dugan Production Corp. API # 30-045-23504  
 Property Name Western Federal Well No. 9 Location: Unit E Section 7 Township 26N Range 11W  
 Well Status(Shut-In or Producing) Initial PSI: Tubing 60 Intermediate 110 Casing 110 Bradenhead 110

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

## PRESSURE

## FLOW CHARACTERISTICS

TIME	Bradenhead			Interm				
	BH	Int	Csg	Int	Csg		BRADENHEAD	INTERMEDIATE
5 minutes			110			Steady Flow		
10 minutes			110			Surges		
15 minutes			110			Down to Nothing		
20 minutes			110			Nothing		
25 minutes			110			Gas		
30 minutes			110			Gas & Water		
						Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_


**5 MINUTE SHUT-IN**

BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

No bradenhead

By

  
 Switcher  
 (Position)

Witness \_\_\_\_\_