



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

RCVD OCT 23 06
OIL CONS. DIV.

DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-16-06 Operator Burlington Mike Murphy API #30-0 45-05902

Property Name Baller Well No. 2 Location: Unit 1 Section 10 Township 26N Range 9W

Well Status(Shut-In or Producing) Initial PSI: Tubing 20 Intermediate Casing 30 Bradenhead X

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>X</u>		<u>30</u>		
10 min	<u>X</u>		<u>30</u>		
15 min	<u>X</u>		<u>30</u>		
20 min	<u>X</u>		<u>30</u>		
25 min	<u>X</u>		<u>30</u>		
30 min	<u>X</u>		<u>30</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD X INTERMEDIATE

REMARKS:

Bradenhead showed no pressure.

By Mike Murphy

Witness

Lease operator

(Position)

E-mail address