

RCUD OCT23'06

CONS. DIV.

DIST. 3



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10-12-06 Operator Burlington API #30-0 45-20053
Property Name Huerfano Unit Well No. 162 Location: Unit D Section 19 Township 26N Range 009W
Well Status (Shut-In or Producing) Tubing 200 Intermediate Casing 215 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>215</u>	Steady Flow	
10 minutes	<u>0</u>		<u>215</u>	Surges	
15 minutes	<u>0</u>		<u>215</u>	Down to Nothing	
20 minutes	<u>0</u>		<u>215</u>	Nothing <input checked="" type="checkbox"/>	
25 minutes	<u>0</u>		<u>220</u>	Gas	
30 minutes	<u>0</u>		<u>220</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Marty Dikenna Witness

MSO
(Position)

E-mail address

PPY