CCUD UCL30'06 DIL CONS. DIV. DIST. 3

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505) 334-6178 FAX: (505) 334-6170

http:\\emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	te of Test 9-28:06 Operator M&G Drilling Company				#30-0 <u>45-</u> 0	6386		
Property Name	MARRON	Well No.	38 Location: Unit	E Section	Tow	nship	27N Range	8W
Well Status (Shut-	In or Producing)	Tubing    9	Intermediate	NA Casing	<u>19</u> Bra	denhead	34	
	OPEN BRA	DENHEAD AND INTE	RMEDIATE TO ATMO	SPHERE INDIVIDU	JALLY FOR 1	5 MINUT	CES EACH	
TIME	PRESSURES:	CASING			BRADE!	NHEAD WED	INTERMEDIATE F	LOWED
5 minutes		19	Steady Flow	***************************************	34			
10 minutes			Surges					
15 minutes			Down to Nothing					
20 minutes		<del></del>	Nothing	· 				
25 minutes			Gas		<del></del>	<del></del>		
30 minutes			Gas & Water		/_			<del> </del>
			Water					
f bradenbead flow	ved water, check all of the d	escriptions that apply belo	w:					
CLEAR _ L	FRESH	_ SALTY S	ULFUR BLA	СК				
MINUTE SHUT	IN BRADENHEAD	34 INTERMEDI	ATE					
REMARKS:								
sy <u>(</u>	ay Rolin	ion.	Witness					
_3_	(Position	n)						

6/26/03- BA = 4 # Smm 53 0