RCVD OCT30'06 OIL CONS. DIV.

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC , NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-7-06	Operator M&G D	rilling Company		API #30	-0 45-06968		
Property Name	KRAUSE	Well No.	22 Location: Unit	0 !	Section	32 Township	28N Range	11W
Well Status (Shut	i-In or roducing)	Tubing	Intermediate	Paring, .	Casing	Bradenhead	<u> </u>	
	OPEN BRADENH	EAD AND INTERM	MEDIATE TO ATMOSPHE	ERE INDIV	IDUALLY F	FOR 15 MINUTES	EACH	
TIME	PRESSURES: INTERMEDIATE	CASING	_			BRADENHEAD FLOWED	INTERMEDIAT	E OWED
5 minutes			Steady Flow	_				
10 minutes	· · · · · · · · · · · · · · · · · · ·	13	Surges	_				
15 minutes	1	13	Down to Nothing	-				
20 minutes		,	Nothing	_				
25 minutes			Gas	-				
30 minutes	:	·	Gas & Water	_				
			Water	_				
If bradenhead flowed water, check all of the descriptions that apply below:								
CLEAR	FRESH	_ SALTY	SULFUR BLA	ск				
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE								
REMARKS:								
Ву	PAULD ROA	RK.	Witness		· · · · · · · · · · · · · · · · · · ·			
	LEASE OF	CRATOR _						