RCVD OCT30'06 OIL CONS. DIV.

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District/III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-7-06	Operator M&G Dril	ling Company	_ API #30-0	45-06982	
Property Name	KRAUSE	Well No.	5 Location: Unit M	Section 32	Township	28N Range 11W
Well Status (Shut-I	n or Rroducing)	Tubing /	Intermediate	Casing	Bradenhead	0
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING		В	RADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		11	Steady Flow		<u>Ó</u>	
10 minutes		11	Surges			
15 minutes		11	Down to Nothing			
20 minutes			Nothing			
25 minutes			Gas			
30 minutes			Gas & Water			
			Water			
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS:						
By DAUD ROARK Witness LEASE OPERATOR						

(Position)