

RCVD OCT30'06

OIL CONS. DIV.

DIST. 3

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnr.state.nm.us/ocd/DistrictIII/3distric.htm>

# BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-9-06 Operator M&G Drilling Company API #30-0 45-07224  
Property Name KRAUSE Well No. 19 Location: Unit D Section 28 Township 28N Range 11W  
Well Status (Shut-In or Producing) Tubing 143 Intermediate - Casing 207 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>207</u>	Steady Flow	<u>0</u>	
10 minutes		<u>207</u>	Surges		
15 minutes		<u>207</u>	Down to Nothing		
20 minutes			<u>Nothing</u>		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By DAVID ROARK Witness \_\_\_\_\_  
LEASE OPERATOR

(Position)