RCVD OCT30°06 OIL CONS. DIV.

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-8-06 Operator M&G Drilling Company			API #30-0 45-23359		
Property Name	KRAUSE	Well No. 71	Location: Unit H	_Section _	32 Township	28N Range 11W
Well Status (Shut-	In or Producing	Tubing	Intermediate	_Casing _		<u> </u>
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
ТІМЕ	PRESSURES: INTERMEDIATE	CASING			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		/33	Steady Flow			
10 minutes		133	Surges	<u></u>		
15 minutes		/33	Down to Nothing			
20 minutes			Nothing			
25 minutes			Gas			
30 minutes		<u> </u>	Gas & Water			
			Water			
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE						
REMARKS:						
					<u>, , , , , , , , , , , , , , , , , , , </u>	and the second s
Γ Γ Γ Γ Γ Γ Γ Γ Γ						
By DAVID COAKK Witness						
(Position)						