RCVD OCT30'06 OIL CONS. DIV.

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410

(505) 334-6178 FAX: (505) 334-6170 http:\\emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-2-06	Operator M&C	G Drilling Company	API #30-0	45-29116	
Property Name	KRAUSE	Well	No. 94 Location: Unit A	Section 28	Township	28N Range 11W
Well Status (Shut-I	n or Producing)	Tubing	Intermediate	Casing	Bradenhead	0
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING		В	RADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow		<u> </u>	
10 minutes			Surges			
15 minutes			Down to Nothing			
20 minutes		,	Nothing	<u> </u>		
25 minutes			Gas			
30 minutes			Gas & Water			
			Water			
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE						
REMARKS:						
						
1						
By DAIOROARK Witness LEASE OPERATOR						

(Position)