RCVD OCT30'06 OIL CONS. DIV.

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	9-/6-06 Operator M&G Drilling Company			API #30-0			
Property Name	KRAUSE	Well No.	11S Location: Unit I	Section 28	Township	28N Range	11W
Well Status (Shut-I	n or Producing	Tubing / / O	Intermediate	Casing	Bradenhead	0	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
TIME	PRESSURES: INTERMEDIATE	CASING		В	RADENHEAD FLOWED	INTERMEDIATE FLO	WED
5 minutes		14	Steady Flow				
10 minutes		17	Surges				
15 minutes		14	Down to Nothing				
20 minutes			Nothing				
25 minutes			Gas				
30 minutes			Gas & Water				·
			Water		····		
If bradenhead flowed water, check all of the descriptions that apply below:							
CLEAR FRESH SALTY SULFUR BLACK							
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE							
REMARKS:							
		<u> </u>				· · · · · · · · · · · · · · · · · · ·	
Ву	DAYIORO	ARK AZZZ	Witness				
	1 tast	JEEN MICK					

(Position)