CCUD NOUT '06. IIL CONS. DIV. DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emmrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test		10-19-06	Operator Them	pson Evangue	Cod API #30-0 <u>045</u>	05467
Property Name		Quitzan		10 Location: Unit P		
Pressure (Shut-In or Producing) Tubing 62 Intermediate — Casing 62 Bradenhead						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	BRADENHEAD	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			62	Steady Flow		NA
10 minutes			62	Surges		NA
15 minutes			62	Down to Nothing		NA
20 minutes			62	Nothing	Nothing	NA
25 minutes			62	Gas		NA
30 minutes			62	Gas & Water		NA
				Water		NA
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
S MINUTE SHUT-IN BRADENHEAD INTERMEDIATE INTERMEDIATE						
Well has been SI and Equalized to sence the						
6th of Oct pending compressor repairs. BH. opend to a very						
slight wisper that died within two seconds						
By Syficial Witness						
LEASE OPERATOR						
(Position)						
E-mail address						