

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTRCVD NOV 10 6
OIL CONS. DIV.

DIST. 3

FORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well ☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator PATINA SAN JUAN, INC.

3a. Address
5802 US HIGHWAY 64 FARMINGTON, NM 874023b. Phone No. (include area code)
505-632-8056

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL, 660' FEL
A Sec 5 - T26N - R3W

5. Lease Serial No.

JICARILLA CONTRACT #97

6. If Indian, Allottee or Tribe Name

JICARILLA APACHE TRIBE

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

TRIBAL 05 #01

9. API Well No.

30-039-29238

10. Field and Pool, or Exploratory Area

Basin Dakota/Blanco Mesa Verde

11. County or Parish, State

RIO ARRIBA CTY, NEW MEXICO

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other REPORT THEFT
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	OF OIL.
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

PATINA SAN JUAN, INC. IS REPORTING A THEFT OF OIL IN THE AMOUNT OF APPROXIMATELY 148.6 BARRELS. THIS THEFT OCCURRED SOMETIME IN THE PERIOD OF JULY 30, 2006 TO IT'S DISCOVERY ON AUGUST 15, 2006 AT 9:00AM. AN INCIDENT REPORT WAS FILED WITH THE JICARILLA TRIBAL AGENCY, TO OFFICER CLARENCE BILAGODY BADGE #1520 ON AUGUST 15, 2006 AT 2:54PM. A COPY OF HIS REPORT IS ATTACHED.

ACCEPTED FOR RECORD

NOV 01 2006

FARMINGTON FIELD OFFICE
BY CD

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Title REGULATORY COMPLIANCE

Signature

Date

08/23/2006

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD

Incident Report 014291

Jicarilla Police Department - ORI 0210300

Incident Date/Time: 07/30/06 00:00
 To: 08/15/06 09:00
 Report Date/Time: 08/15/06 14:54

Description: THEFT
 File#:

Complainant: VIGIL,GREG
 Address: 537
 Address:
 City/State: DULCE,
 Phone: 505-486-4851

DOB:
 Race:
 Sex:
 Ethnic:
 Height: ' 0"
 Age:
 Resident:
 Hair:
 Eyes:
 Weight: 0

Location of Occurrence
 Address: 2.9 MI E/O 537 MP 28
 Address:
 City/Cross Street: DULCE /

Employer:
 Address:
 Address:
 City/State: ,
 Phone: - -

Occupation:

STOLEN PROPERTY SHOP LIFT

Completed

Person(s) Involved:

Type	Name	DOB	Address	City/State	Phone
Victim	PATINA-NOBLE ENERGY		5802 US HWY 64	FARMINGTON,NM 87401	- -

Location: 537 - SR 537

Time Arrived: 14:03

Time Cleared: 14:43

Burglary Crimes

Entry Method:
 Entry Point:
 Instrument:
 Inc. Activity:

Exit Point:
 Neighborhood:
 Safe Entered:

Referral:
 Children:
 Evidence Taken: Photo: Fingerprint(s): Other:

Inv Assgn:

Inv Due:

Approved: 08/16/06

Status: Active Exp. Cld. Status: Status Date:

Investigator: -

Reporting Officer: 1520 - CLARENCE BILAGODY

Supervisor: 1506 - RODNEY JOHNSON

Entered By: -

Records: -

Addendum Codes: /

Copies To:

News Media

VICTIM/SUBJECT SECTION

Victim		1	
Name:	PATINA-NOBLE ENERGY	Injuries	DOB :
Addr:	5802 US HWY 64	1:	Race:
Addr:		2:	Sex :
City:	FARMINGTON,NM 87401	3:	Age : -
Phone:	- - (H) - - (W)	4:	Ethn:
SSN:	- -	5:	Resd: Unknown
Type:	Business		

PROPERTY/VEHICLE SECTION

Plate #	State	Type	VIN	Year	Make	Model	Colors	Style	Reason
Loss Type	Qnt	Make, Model, Style	Description	Serial #	Value	Rec Date	Rec Value		

Incident Report 014291
Jicarilla Police Department

Incident Date/Time: 07/30/06 00:00
To: 08/15/06 09:00
Report Date/Time: 08/15/06 14:54
1 Stolen 149

Description: THEFT
File#:

BARRELS OF OIL 0.00 0.00

Jicarilla Apache Police Department

Incident Narrative

014291

SYNOPSIS:

On 8-15-2006 at approximately 0900 hours, Greg Vigil, Lead Pumper for the Patina Oil and Gas Corporation discovered 148.6 barrels of oil was stolen from a storage tank approximately 2.9 miles East of highway NM 537 milepost 28.3, South of Dulce, N.M. within the boundary of the Jicarilla Apache reservation.

INVESTIGATION:

On 8-16-2006 at approximately 1403 hours, I arrived at the location where the oil was stolen. This was in rough terrain in a remote area 2.9 miles East of highway NM 537 from milepost 28.3. The well site # Tribal 05 #1.

I made contact with Greg Vigil. He is employed with the Patina-Nobele Energy Oil and Gas Corporation, as a Lead Pumper. Vigil stated that the well and equipment belong to the Patina Corps. The Jicarilla Apache Tribe collects royalties from the gas and oil. He states that this Oil well site collects Gas and Oil, and collects water, but are all separated into separate storage areas. He stated he checked the Oil tank on July 30, 2006. There were 11.6 heights of oil in the tank. On August 15, 2006 at 9:00 am, he checked the tank and discovered there were only 4.1 heights in the tank. He states that 7.5 heights of oil are missing from the tank. This adds up to 148.6 barrels of oil which equals approximately \$10,402.00 dollars. Calculated by \$70.00 dollars a barrel.

Mr. Vigil has checked with the dispatcher at the Giant Refinery in Bloomfield, N.M. (505) 632-8024. He asked if the company had pumped the oil from the tank at that well site. They did not have any record that oil was pumped from that well. Vigil stated that their Corps. Will call Giant to pump oil from Oil Wells, then Giant will perform the work. There was no such request made.

Mr. Vigil states there are indications that the Oil was more than likely stolen. The seal from the oil pump spout was missing. It was not recovered on site. He stated that there were big truck tire tracks which were much more visible yesterday. It appeared the truck drove up beside the fence. There was an imprint of the hose, where the hose was laid under the fence. It takes approximately 30-45 minutes to pump the missing oil from the tank. He states the suspect (s) knew what they were doing. They probably had to use a truck with a barrel load capacity of 80 barrels.

Mr. Vigil states this is the first time, he knows of that oil has been stolen from any of their well sites.

After contact with Vigil, I photographed the area, and the well site, and tank that the oil was stolen from. The tank # is G1-10734.

Jicarilla Apache Police Department

Incident Narrative


014291

SUPERVISOR NOTIFICATION:

On 8-16-2006 at approximately 1530 hours, I contacted Sergeant Rod Johnson. I gave him details of the case. The amount of \$10, 402.00 dollars falls under the major crimes investigation. Sergeant Johnson's instructions were to refer the case to Special Investigator Esteban Blanco for further investigation.

DISPOSITION:

This case will be referred to Investigator E. Blanco on 8-16-2006.


Clarence Bilagody #1520

Jicarilla Apache Police Department


Incident Narrative

014291

Photo Log:

August 16, 2006, between 1430-1440 hours, I photographed the following pictures at the Well Site 05 #1, approx. 2.9 mi. East of NM 537 Milepost 28.3, South of Dulce, N.M.

1. Photo of well site-overview.
2. View of road intersecting and leading to the well site.
3. View of other road leading from intersection to the south
4. View of intersection
5. View of Well identification sign
6. View of well pump-south of tank
7. View of well-south of tank
8. View of gas pump next to well water tank
9. View of water and oil tank
10. View of oil storage tank # G1-10734
11. View of top of oil tank
12. View of suspect tire tracks
13. Close up view of suspect tire tracks
14. View of impression on ground under fence. Hose was laid
15. View of impression on ground



Investigator Clarence Bilagody #1520