



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

RCVD NOV 6 '06

OIL CONS. DIV.

DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

10/30/06

Operator

KUTKUT

API #

30 045 31713

Property Name

ANGEL PEAK 9#185

Location: Unit

J

Section

9

Township

27N

Range

17W

(Well Name and Number)

Pressure (Shut-in or Producing)

Tubing

44

Intermediate

—

Casing

44

Bradenhead

0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	44					
10 minutes	0	44					
15 minutes	0	44					
20 minutes	0	44					
25 minutes	0	44					
30 minutes	0	44					
5 minute SI	0	44					
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in

Bradenhead

0

Intermediate

—

REMARKS:

by

LUCKY NASA THA

Witness

PUMPA

(Position)