

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

CO

CONSERVATION DIVISION

CONSERVATION DIVISION

CONSERVATION DIVISION

CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178

FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)		
Date of Test 12-11-06 Operator Dwon Energy API #30-0 45 27340		
Property Name 163 Www Nosa Swb Location: Unit Nosection 36 Township 3 Mange 8 W		
Well Status (Shut-In or Producing) Tubing 150	Intermediate //A Casing 2 Bradenh	ead
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH		
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Steady Flow	
10 minutes	Surges	
15 minutes	Down to Nothing	
20 minutes	Nothing	
25 minutes	Gas	
30 minutes	Gas & Water	
	Water	
If bradenhead flowed water, check all of the descriptions that apply below:		
CLEAR FRESH SALTY SULFUR BLACK		
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE Y		
REMARKS: Volhung When Dened-		
1.7		
BN DATA	Witness / Mills (walk)	in 8
De Governan		
(Position)		
E-mail address		