



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 12-11-06 Operator Devon Energy Prod API # 30-0 39-24236

Property Name DEBU Sims Mesa Well # 1 Location: Unit E Sec 10 Twn 30 Rge 7

Land Type:

State _____
Federal ☒
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N) (N) TA Expires: _____

Casing Pres. 0
Bradenhead Pres. 0
Tubing Pres. 1245
Int. Casing Pres. N/A

Tbg. SI Pres. _____
Tbg. Inj. Pres. _____

Max. Inj. Pres. _____

Pressured annulus up to 562 psi. for 30 mins. Test passed failed

REMARKS:


Packer set at 7290
Rose & fell back to 560

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

Foreman
(Position)

Revised 02-11-02



ROAD DECLIV

01 CONVS. D

DIST. 3

PRINTED IN U.S.A.