



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 12-18-06 Operator Merrion OEG API # 30-0 45-30922


Property Name Putty Lady 30-11-34 Well # 1 Location: Unit J Sec 34 Twn 30 Rge 11

Land Type:

State _____
Federal _____
Private ☒ _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal ☒ _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____



Temporarily Abandoned Well (Y/N): _____ TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. 0 Tbg. Inj. Pres. _____
Tubing Pres. 0
Int. Casing Pres. N/A

Pressured annulus up to 540 psi. for 30 mins. Test passed/failed

REMARKS:

Packer set at 3759

Agua-Moss

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02

Agua Moss LLC
Wellbore Schematic
Pretty Lady 30-11-34
Current Wellbore Configuration

Location: 1760' fsl & 1475' fel (nw se)
 Sec 34, T30N, R11W, NMPM
 San Juan Co, New Mexico

Date: December 18, 2006

Elevation: 5789' GL
 5802' RKB

Injection Zone: Mesaverde
 Prepared by: Connie Dinning
 Updated by: Tyson Foutz

