

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

| |
|---|
| WELL API NO. 30-039-29923 |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. RCVD DEC 22 2006 OIL CONS. DIV. |
| 7. Lease Name or Unit Agreement Name San Juan 29-6 Unit |
| 8. Well Number #74B |
| 9. OGRID Number 217817 |
| 10. Pool name or Wildcat Blanco MV |

| | |
|---|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other | |
| 2. Name of Operator ConocoPhillips Company | |
| 3. Address of Operator P.O. Box 4289, Farmington, NM 87499-4289 | |
| 4. Well Location Unit Letter <u>J</u> : <u>1865</u> feet from the <u>South</u> line and <u>1715</u> feet from the <u>East</u> line Section <u>20</u> Township <u>29N</u> Range <u>6W</u> NMPM Rio Arriba County | |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6419' | |

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Spud Report ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/18/06 MIRU Mote #211. Spud 12 1/4" @ 1300 hrs. Drilled 262'. Circ hole. RIH w/ 11 jts, 9 5/8, 32.3#, H-40 STC casing set @ 257'. Preflush w/ 10bbls FW. Pumped 77 sx (124 cf - 22 bbls slurry) w/ 20% Fly-Ash. Dropped plug and displaced w/ 17 bbls FW. Circ 3 bbls cement to surface. WOC. NU BOP. Will show PT on next report.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Kandis Roland TITLE Regulatory Technician DATE 12/21/06
Type or print name Kandis Roland E-mail address: kburns2@br-inc.com Telephone No. 505-326-9743

(This space for State use)

APPROVED BY A. Villanueva TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #1 DATE DEC 22 2006
Conditions of approval, if any:

B