



**NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT**

**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170**

[www.emmrd.state.nm.us/ocd/District 3/district3.htm](http://www.emmrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

RCVD DEC 28 '06
OIL CONS. DIV.

DIST. 3

Date of Test 12-14-06 Operator Huntington Energy API #30-0 39-29272

Property Name CHU Well No. 457 Location: Unit 5W Section 36 Township 25 Range 7

Well Status (Shut-In or Producing) Tubing ☒ Intermediate ☐ Casing ☒ Bradenhead ☒

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				
	BRADENHEAD	INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	<u>0</u>		<u>490</u>	Steady Flow	
10 minutes	<u>0</u>		<u>490</u>	Surges	
15 minutes	<u>0</u>		<u>485</u>	Down to Nothing	
20 minutes	<u>0</u>		<u>475</u>	Nothing ☒	
25 minutes	<u>0</u>		<u>465</u>	Gas	
30 minutes	<u>0</u>		<u>450</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN BRADENHEAD ☒ INTERMEDIATE ☐

REMARKS:

Well was hanging while testing
No Flow! No Press

By Steve Imogene

Witness

(Position)

Lease Oper

E-mail address